



this inside end panel is incorrect on the earlier drawings. It should be 3" narrower and sit inside the frame by 1 1/2" so the inside side panels will slide up to the end frame.

Sweet Haven Railroad addendum 3 exploded view of boxcar (no scale)

This addendum is issued because I was having trouble visualizing how some of the parts went together. If I was having trouble, I figured you might have the same problem. As it is, I found an error as noted above.